



6228

RUST PROTECTIVE COATING - SATIN BLACK

KATS 6228 is a water based rust preventive coating that is formulated using plant base polymer technology to provide outstanding protection against corrosion on both ferrous and nonferrous metals. The product leaves an attractive black satin finish. The normal duration of protection is up to 3 years.

The surfaces to be protected should be clean and dry. Apply KATS 6228 in a good ventilated area without excessive wind. Before using, review SDS and wear proper gear.

KATS 6228 can be applied using an airless sprayer or HVLP/conventional air spray applicator assisted with fluid pressure pot system.

Ambient/Surface temperature.....45° - 100°F (7° - 38°C)
 Ideal Surface Temperature60° - 80°F (16° - 27°C)
 Note: Insure the coating is dry before exposing to the elements. To minimize temperature/humidity variables, heated force drying is recommended to improve early water resistance.

Wet Film Thickness5 - 10 mil (127 - 254 microns)
 Dry Film Thickness1 - 2 mil (25.4 - 50.8 microns)
 Typical Coverage.....160 - 320 ft²/gal (3.9 - 7.9 m²/l).

Shelf Life.....12 months from date of manufacture
 Storage Temperature.....40° - 80°F

Agitate before and during use.

BENEFITS:

- 0.7 lb/gal (84 gm/liter) VOC
- HAPs-free
- Excellent adhesion to various substrates
- Early water resistance
- Protects up to 3 years
- Quick drying
- Contains no oil or petroleum
- No fire hazard
- Environmentally safe

APPLICATIONS:

Use KATS 6228 to prevent rust and corrosion on metal surfaces. Typical applications include:

- Vehicle underbody coating
- Protection of machine components during storage
- Protection of metal stock
- Protection of outdoor stored gears

TEST METHOD	DESCRIPTION	TYPICAL CHARACTERISTIC
ASTM D-2247	Humidity Exposure	Passed 500 hours with less than 0.01% surface rust.
GM 9508P	Gravelometer (tests impact protection)	Pass
ASTM B-117	Salt Spray Test	Passed at 50 hours exposure with less than 0.01% surface corrosion.
ASTM D-2243	Freeze and Thaw Stability, Cycles Passed	3
ASTM D-2196 Modified	Brookfield Viscometer Spindle #4 @ 72°F (22°C) and 60 RPM, cps	3,000 - 10,000
ASTM D-1475	Density	8.7 lb/gal (1.044 g/cm ³)

The above are average values. Minor variations which do not affect product performance are to be expected in normal manufacturing.

PACKAGING

260 Gallon Totes	55 Gallon Drums	5 Gallon Pails
------------------	-----------------	----------------

APPLICATION INSTRUCTIONS

1. If the surfaces of the vehicle have excess dirt or airborne contaminants, wash or pre-rinse and dry the vehicle before application of the transit coating.
2. Check the surface temperature of the vehicle either with a surface thermometer or by hand. Ideal temperature should be 60° - 80°F (15° - 27°C). If necessary, either cool or warm the surfaces.

Note: It can be applied over area with higher temperature that can shorten the dry time exponentially, but flowability/penetration capability may be compromised.

3. Apply the coating in a shaded area that is protected from excess wind or from outdoor moisture, if possible. Insure the area is well ventilated as a standard protocol. Down draft, if working in a pit, is recommended to insure catching any overspray.
4. Use a water based compatible airless spray pump system. If this is not available, a HVLP spray applicator with pressure feed system can be used. Also, extension wand can be utilized on difficult to reach areas.



Equipment	Details		
Pump		Graco Dura-Flo or Similar	Graco Xtreme X30 or Similar
	Output per Cycle	220 cc	220 cc
	Motor Size	NXT 3400	NXT 3400
	Max. Working Pressure (psi)	3170	3150
	Output at 60 CPM (gpm)	3.4	3.4
Fluid Pressure	1000 - 2000 psi		
Hose	¼ in x 50 ft Graco BluMax II or similar		
Spray Applicator	Graco XTRA, Graco SG Series or similar		
Tip Size	.011 - .015 in Graco RAC 5 or similar		

Note: Clean the equipment with clean water right after application when the coating is still wet. Do not let the coating dry up.

5. Apply the coating by keeping a constant distance of 8 - 9 inches (20 - 23 cm) from the nozzle to the vehicle's surfaces. Always move the applicator parallel to the areas being sprayed while holding the applicator at a perpendicular angle relative to those same spray surfaces.
6. Do not move the recently sprayed vehicle into a rainy, snowy, or dirty environment until the coating has dried (air-assisted drying system, e.g. forced heated air or oven, 1 - 3 minutes; unassisted, e.g. ambient air drying with air movement, 10 - 15 minutes).

Note: For any overspray near unwanted area, you may use diluted KATS 8077 solution to clean off. Insure to rinse the area well to remove any soapy residue and dry with clean towel.

7. After the coating has dried, inspect the film to make sure it is continuous and consistent. If areas were missed during the application, apply the coating to those areas.

KATS Coatings is owned and operated by Ritek, Inc. We warrant our products to be of good quality and will replace or, at our discretion, refund the purchase price of any products proved defective. Satisfactory results depend not only upon quality products, but also upon many factors beyond our control. Therefore, except for such replacement or refund, RITEKS MAKES NO WARRANTY OR GUARANTEE, EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF FITNESS FOR A PARTICULAR PURPOSE OR MERCHANTABILITY. RITEKS shall have no other liability with respect thereto. User shall determine the suitability of the products for the intended use and assume all risks and liability in connection there with. The information provided herein is based on technical data that Ritek, Inc. believes to be reliable. RITEKS, Inc. makes no representation or warranty as to the completeness or accuracy thereof and assumes no liability resulting from its use for any claims, losses, or damages of any third party. Recipients receiving this information must exercise their own judgment as to the appropriateness of its use and it is the user's responsibility to assess the material's suitability (including safety) for a particular purpose prior to such use.

